



SERVICE NOTE No. 2/2014



Please inspect the condition of the gear lever mounting bracket, we have seen this bracket fail and break off the chassis since the introduction of the sequential gearbox. Weld and brace if required and inspect on a regular basis.

Date of issue 24/02/2014