



Service Note No. 3/2014



It is recommended lifting the rear wishbones to avoid failure.

Inspect the rear wishbones before each event.

Date of issue 24/02/2014