



Service Note

Cars fitted with billet aluminium uprights, it's very important when replacing drive shafts or dummy flanges the Adaption Ring must be refitted.



Issue date 9th February 2023.

