



## SERVICE NOTE

When preparing your car, check the carburettor mounting for signs of splits in the rubber.



Issue date 15/11/18.