



SERVICE NOTE

1. Before each event, it is recommended that you check the rose joints are completely free at either end of the gear linkage and the rose joint that bolts into the gearbox (3 in total) if in doubt, replace them. Also, please make sure that the bolts securing the rose joints are NOT tight. Please see picture:



2. It is also recommended that you remove and inspect the right engine mounting, check for any signs of cracking, either replace or repair/strengthen as required. Please see picture:

