



Service Note. No.1/2014

Please note, it is recommended that your sequential gearbox has the annual service before the start of the season. This is not a refresh, it is a complete strip down, including the removal of the differential and the check/replacement of diff and pinion bearings.

We have also received 3 upgrades from Sadev, so this could be done at the same time. Please be aware that none of the above work can be carried out at the circuit as specialist tools are required.

Date of issue 17/02/2014