



Service Note No. 1/2015

On your pre-race preparation of your car, please check and make sure the end plate on the Pro Shift actuator is tight before each event.

Please see picture below.



Date of issue 08/06/2015